

## Storage and delivery of PET strapping tapes (conditions)

### General information:

Proper storage of PET- strapping tapes is very important for later use.

### Therefore the following advice must be considered:

- Do not expose goods to humidity and direct sunlight
- Store goods in a dry place at a temperature between 15°C and 35°C
- Keep goods away from dust and vibrations
- Avoid dust, direct heat, direct contact to flames and ignition sources
- Store goods only in original packing and open just before using – also valid for pallet packing
- If stored under cold conditions – especially in unheated warehouses goods must be taken into production facility at least 24 hours preferably 48 hours before processing. It is recommended to take out stretch film for conditioning

### If stored outside the following additional advice must be considered:

- Packaging outside must be done by water protected awning; direct sunlight must be avoided; air circulation should be possible under awning to avoid heat accumulation
- Awnings must also protect goods against rain and / or snow

### Delivery / Transport:

- Do not stack, turn, untie or dismantle pallets during transport
- For transport (parcel service, single parcels) do not turn spool box upside down

### Storage

- Do not transport and store spools upside down
- Recommended maximum usage time should not be more than 6 months after delivery date. FiFo principle is valid.

The information provided is based on our experience and knowledge and is not intended as a product description for safety requirements. It is not intended as a guarantee for specific properties. According to test results of independent laboratory, the products we deliver meet the standards of the European Parliament laid down in directive 2002/95/EC and 2003/11/EC as well as in the RoHS directive (Restriction of Hazardous Substances).

However, we do not generally exclude the possibility of trace contaminants in these materials.